

## S29393

45W/LED/HID/5K/100-277V/EX39 45 watt - LED HID Replacement; 5000K; Mogul extended base; 100-277 volts

## Features

- High Lumen Omni-directional LED for Industrial / Commercial applications
- Replaces HID, CFL, and Incandescent
  Ballast by-pass Direct wire only 100V 277V
  UL approved for totally enclosed fixtures
- Wet location rated
- For outdoor & indoor use
- Base up, base down or horizontal operation
- Emits no UV light / Contains no mercury (Hg)
- 5 year limited warranty
- Classified under UL 1598C

## Additional Technical Specifications

- Power Factor >0.9
- Operating temperature range -20°C to 65°C
- Operating Frequency 50-60HzWorking Voltage AC90-305V

Minimum Compartment Size						
Length	Width	Depth				
17.3 inch	9.25 inch	9.25 inch				

Optional accessory: In-line surge protector 80-929

This item has been discontinued. Possible replacement:

• S39393



S29393

Item	Product	UPC Input		Watts	Operating	Incandescent	Fluorescent	
Number	Line	Voltage			Frequency	Equivalent	Equivalent	
S29393	Hi-Pro	045923296734	100 - 277	45	50/60Hz	300W	65W	

HID E	quivalen	t Base	ANSI Base	Lamp Code			Dimmable/Non- Dimmable		Finish	MOL In Inches	MOD In Inches	
17	75W	Mogul Extended	EX39	45W/LED/HID/5K/100- 277V/EX39		No	Non-Dimmable		White	10-3/4"	3.69"	
Ini Lun	tial nens	Average Rated Hours	Kelvin Temp	Color CRI Beam Spread Burning			ng Position	on Operating Temperature				
60	000	50000	5000	Natural Light	80+	300	Up or Down Operation Only		-20C	-20C (-4F) to a maximum of +65C (+149F)		
Pack	Packaç Type	CEC Status	DLO	C ID:	RoHS Complia		lassific	ation	Warranty	St	atus	Suggested Substitute
12	Вох	Lawful for sale in California	PLJ1C8E DLC Sear		Yes		cULus - Wet Location Rated		5 Year Limited	Disco	ntinued	<u>S39393</u>



National Toll-Free: 800.43.SATCO (800.437.2826) www.satco.com Distribution Centers: New York, Florida, Texas, Washington, California, Puerto Rico Corporate Offices: 110 Heartland Blvd., Brentwood, NY 11717 800.437.2826 631.243.2022 Fax 631.243.2027



©2012, Satco Products, Inc. Not responsible for typographical errors. 06/12 S1051